


These pins to DB-9 connector


These pins to STM32

Note:

1. C4 should be place close to the U3.
2. 3x100uF near its IC's pins.




Current sensor



Board power

Power for load (spindle, laser, etc)



Power for scheme

