


GPIO15	GPIO0	GPIO2	Mode	Comments
L	H	H	Flash	Boot from SPI Flash
L	L	H	UART	Program via UART (TX/RX)
H	X	X	SDIO	Boot from SD-card



- 3V Status LED
- Status switch
- Weight sensor
- Voltage sensor
- Only for programming