



Microcontroller





Revision 2




ANAREF – Silicon bug CHIP003-161
VDDANA as the DAC Reference non-functional.

RESET – Silicon bug HIP003-159
Internal pull-up non-functional.

| Power




USB




Source connected to a legacy device port.

The CC pins are pulled-down to GND Rd ($5.1\text{ k}\Omega \pm 20\%$) to indicate that VBUS should be supplied by the host.

Orientation Sensor




Accelerometer + Gyroscope + Sensor Hub



Magnetometer

Mechanical / Production



V2 axis
Versio Duo
Orientation Sensor

Rev: 6
Id: 1/1
Sheet: Root
Date: 2025-11-16