

Report Number: FIR2024005

Date of Report: 2024-11-08

Police Station: Jubilee Hills Police Station, Hyderabad

Complainant Details

Name	Vikram Mehta
Address	Banjara Hills, Hyderabad
Contact	+91 9876543120

Accident Details

Date and Time	2024-11-07 22:10
Location	Road No. 36, Jubilee Hills
Type	Two-Wheeler Collision with Car
Vehicle	Bajaj Pulsar (AP10BC1234)
Driver License	AP456789123
Driver Age/Gender	26 / Male

Injury/Damage Details

Injuries	Fractured left leg
Property Damage	Bike's front wheel and headlight damaged

Witness Information

Name	Ramana Rao
Contact	+91 9098765432

Narrative Summary

The accident involved a two-wheeler and a car near the Jubilee Hills crossing. According to witnesses, Mr. Mehta, who was on the bike, was traveling at high speed and lost control while attempting to overtake the car. As a result, his bike collided with the car's rear bumper, causing Mr. Mehta to fall and sustain injuries. Skid marks and damage assessments matched the statements, confirming the high-speed impact. The car driver was compliant with road regulations, and the blame was attributed to Mr. Mehta's negligence.

Officer Details

Name	Inspector Subhash Rao
Badge	INSP-091

Estimate for FIR: FIR2024005

Vehicle	Bajaj Pulsar
Registration	AP10BC1234

Repair Details

Repair Item	Parts Cost (■)	Labor Hours	Labor Cost (■)
Bike front wheel replacement	4,000.00	1	500.00
Bike headlight replacement	2,000.00	1	500.00

Cost Summary

Parts Cost	■ 6,000.00
Labor Cost	■ 1,000.00
GST (18%)	■ 1,260.00
Total Cost	■ 8,260.00

Disclaimer: This is an estimated cost based on standard repair rates. Actual costs may vary depending on the exact extent of damage, parts availability, and additional damage discovered during repairs. All prices include standard parts and labor charges. Additional charges may apply for premium/imported parts.