


Spider 1.0 +  
BTT 2209 –  
Voron 2.4 build




# What goes where?





1. B-Motor
2. A-Motor
3. Z0 Stepper - Front Left
4. Extruder
5. Z1 Stepper - Rear Left
6. Z2 Stepper - Rear Right
7. Z3 Stepper - Front Right

8. Raspberry
9. Hotend Heater
10. SSR
11. 24V to SSR
12. 24V Power Supply and RasPi
13. Hotend Fan
14. Part Cooling Fan
15. Case Fan
16. Thermistor Hotend
17. Thermistor Bed
18. Endstop X
19. Endstop Y
20. Probe
21. Endstop Z





# Bridging Z2-Mot

It is hard to see but Jumpers need to be placed in the JST connector.





# Jumper for TMC 2209 (also BTT)



# E4-Mot

V2 with the printer.cfg from FYSETC GitHub  
do not need E4-Mot.  
So no Stepper driver needed.

