XS2 priority threads

Threads can be set to have priority

- Normal use of priority threads has fewer than five priority threads
 - Priority thread is guaranteed 100 MIPS (assuming 500 MHz)
 - Other threads are scheduled around it.
- MIPS rates for 1-8 threads with 0-4 priority threads:

```
Total number of threads
prio 1 2 3 4 5 6 7 8
0 100 100 100 100 100 83 71 62
1 100 100 100 100 80 66 57
2 100 100 100 75 60 50
3 100 100 66 50 40
```

• First row is case without priority threads.



100

50 33 25