





TODO: Verify 5V LDO max power



TODO: Add pull up/down for unused inputs.

TODO: Does accelerator's int1 need pull up?

