

STRUCTURAL CRACK ANALYSIS & MEASUREMENT REPORT

Original Image

Report generated using CrackVision – by Om Ray

File: C:\Users\1225z\OneDrive\Desktop\test1.jpg

Prediction: crack



Confidence: 99%

Manual Length: 10.22 mm

Width (est): 1.2 mm

Calibration: 54.776566 mm/pixel

Generated: Wednesday, 05 Nov 2025



Remarks:

[2025-11-05 16:39:13] Manual measurement: 10.22 mm