

Test Report

樣品型號(Style/Item No.)

頁數(Page): 1 of 14 日期(Date): 2017/06/01 號碼(No.): CE/2017/55480

鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號 NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

以下測試樣品係由申請廠商所提供及確認 (The following sample(s) was/were submitted and identified by/on behalf of the applicant as):

鴻星電子股份有限公司 (HOSONIC ELECTRONIC CO., LTD.) 送樣廠商(Sample Submitted Bv) 樣品名稱(Sample Description) SMD CRYSTAL SERIES AND SMD CRYSTAL OSCILLATOR SERIES SEAM SEALING CRYSTAL AND SMD OSC/VCXO/PECL/LVDS

收件日期(Sample Receiving Date) 2017/05/24

測試期間(Testing Period) 2017/05/24 TO 2017/06/01

測試結果(Test Results) : 請參閱下一頁 (Please refer to following pages).



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-Document.aspx. Attention at drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document developed at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document developed at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document developed at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document developed at the intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document are the company at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document are the company at the co



Test Report

號碼(No.): CE/2017/55480 日期(Date): 2017/06/01

頁數(Page): 2 of 14

鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號

NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

測試結果(Test Results)

測試部位(PART NAME)No.1 : 整體混測 (MIXED ALL PARTS)

測試項目 (Test Items)	單位 (Unit)	測試方法 (Method)	方法偵測 極限值 (MDL)	結果 (Result) No.1
鎘 / Cadmium (Cd)	mg/kg	参考IEC 62321-5 (2013),以感應耦合 電漿原子發射光譜儀檢測. / With reference to IEC 62321-5 (2013) and performed by ICP-AES.	2	n. d.
鉛 / Lead (Pb)	mg/kg	參考IEC 62321-5 (2013),以感應耦合 電漿原子發射光譜儀檢測. / With reference to IEC 62321-5 (2013) and performed by ICP-AES.	2	n. d.
汞 / Mercury (Hg)	mg/kg	参考IEC 62321-4 (2013),以感應耦合 電漿原子發射光譜儀檢測. / With reference to IEC 62321-4 (2013) and performed by ICP-AES.	2	n. d.
六價鉻 / Hexavalent Chromium Cr(VI) (◆)	mg/kg	参考IEC 62321-7-2 (2017),以UV-VIS 檢測;參考IEC 62321-5 (2013),以 ICP-AES檢測. / With reference to IEC 62321-7-2 (2017) and performed by UV-VIS.; With reference to IEC 62321-5 (2013) and performed by ICP-AES.	8	n. d.
銻 / Antimony (Sb)	mg/kg	參考US EPA 3052 (1996),以感應耦合 電漿原子發射光譜儀檢測. / With reference to US EPA 3052 (1996). Analysis was performed by ICP-AES.	2	n. d.
砷 / Arsenic (As)	mg/kg	参考US EPA 3052 (1996),以感應耦合 電漿原子發射光譜儀檢測. / With reference to US EPA 3052 (1996). Analysis was performed by ICP-AES.	2	n. d.



Test Report

號碼(No.): CE/2017/55480 日期(Date): 2017/06/01

頁數(Page): 3 of 14

鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號

NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

測試項目 (Test Items)	單位 (Unit)	測試方法 (Method)	方法偵測 極限值 (MDL)	結果 (Result) No.1
鉞 / Beryllium (Be)	mg/kg	参考US EPA 3052 (1996),以感應耦合 電漿原子發射光譜儀檢測. / With reference to US EPA 3052 (1996). Analysis was performed by ICP-AES.	2	n. d.
多溴聯苯總和 / Sum of PBBs	mg/kg		-	n. d.
一溴聯苯 / Monobromobiphenyl	mg/kg] [5	n. d.
二溴聯苯 / Dibromobiphenyl	mg/kg] [5	n. d.
三溴聯苯 / Tribromobiphenyl	mg/kg] [5	n. d.
四溴聯苯 / Tetrabromobiphenyl	mg/kg] [5	n. d.
五溴聯苯 / Pentabromobiphenyl	mg/kg]	5	n. d.
六溴聯苯 / Hexabromobiphenyl	mg/kg]	5	n. d.
七溴聯苯 / Heptabromobiphenyl	mg/kg]	5	n. d.
八溴聯苯 / Octabromobiphenyl	mg/kg]	5	n. d.
九溴聯苯 / Nonabromobiphenyl	mg/kg	 参考IEC 62321-6 (2015),以氣相層析	5	n. d.
十溴聯苯 / Decabromobiphenyl	mg/kg	/質譜儀檢測. / With reference to	5	n. d.
多溴聯苯醚總和 / Sum of PBDEs	mg/kg	IEC 62321-6 (2015) and performed	_	n. d.
一溴聯苯醚 / Monobromodiphenyl ether	mg/kg	by GC/MS.	5	n. d.
二溴聯苯醚 / Dibromodiphenyl ether	mg/kg]	5	n. d.
三溴聯苯醚 / Tribromodiphenyl ether	mg/kg	1	5	n. d.
四溴聯苯醚 / Tetrabromodiphenyl ether	mg/kg		5	n. d.
五溴聯苯醚 / Pentabromodiphenyl ether	mg/kg		5	n. d.
六溴聯苯醚 / Hexabromodiphenyl ether	mg/kg		5	n. d.
七溴聯苯醚 / Heptabromodiphenyl ether	mg/kg		5	n. d.
八溴聯苯醚 / Octabromodiphenyl ether	mg/kg		5	n. d.
九溴聯苯醚 / Nonabromodiphenyl ether	mg/kg		5	n. d.
十溴聯苯醚 / Decabromodiphenyl ether	mg/kg		5	n. d.



Test Report

號碼(No.): CE/2017/55480 日期(Date): 2017/06/01

頁數(Page): 4 of 14

鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號 NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

測試項目 (Test Items)	單位 (Unit)	測試方法 (Method)	方法偵測 極限值 (MDL)	結果 (Result) No.1
鄰苯二甲酸丁苯甲酯 / BBP (Butyl Benzyl phthalate) (CAS No.: 85-68-7)	mg/kg		50	n. d.
鄰苯二甲酸二丁酯 / DBP (Dibutyl phthalate) (CAS No.: 84-74-2)	mg/kg		50	n. d.
鄰苯二甲酸二 (2-乙基己基)酯 / DEHP (Di- (2-ethylhexyl) phthalate) (CAS No.: 117-81-7)	mg/kg		50	n. d.
鄰苯二甲酸二異丁酯 / DIBP (Di- isobutyl phthalate) (CAS No.: 84-69- 5)	mg/kg	參考IEC 62321-8 (2017),以氣相層析 儀/質譜儀檢測. / With reference to IEC 62321-8 (2017). Analysis was performed by GC/MS.	50	n. d.
鄰苯二甲酸二異癸酯 / DIDP (Di- isodecyl phthalate) (CAS No.: 26761- 40-0; 68515-49-1)	mg/kg		50	n. d.
鄰苯二甲酸二異壬酯 / DINP (Di- isononyl phthalate) (CAS No.: 28553- 12-0; 68515-48-0)	mg/kg		50	n. d.
鄰苯二甲酸二正辛酯 / DNOP (Di-n-octyl phthalate) (CAS No.: 117-84-0)	mg/kg		50	n. d.
鄰苯二甲酸二甲酯 / DMP (Di-methyl phathalate) (CAS No.: 131-11-3)	mg/kg		50	n. d.
鄰苯二甲酸二乙酯 / DEP (Di-ethyl phthalate) (CAS No.: 84-66-2)	mg/kg		50	n. d.
鄰苯二甲酸二戊酯 / Di-n-pentyl phthalate (CAS No.: 131-18-0)	mg/kg		50	n. d.
鄰苯二甲酸二環己酯 / DCHP (Di- cyclohexyl phthalate) (CAS No.: 84- 61-7)	mg/kg		50	n. d.
鄰苯二甲酸二苯酯 / DPhP (Diphenyl phthalate) (CAS No.: 84-62-8)	mg/kg		50	n. d.



Test Report

號碼(No.): CE/2017/55480 日期(Date): 2017/06/01

頁數(Page): 5 of 14

鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號

NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

測試項目 (Test Items)	單位 (Unit)	測試方法 (Method)	方法偵測 極限値 (MDL)	結果 (Result) No.1
鄰苯二甲酸二苯甲基酯 / DBzP (Dibenzyl phthalate) (CAS No.: 523- 31-9)	mg/kg		50	n. d.
鄰苯二甲酸二異辛酯 / DIOP (Di- isooctyl phthalate) (CAS No.: 27554- 26-3)	mg/kg	參考IEC 62321-8 (2017),以氣相層析	50	n. d.
鄰苯二甲酸二丙酯 / DPrP (Di-propyl phthalate) (CAS No.: 131-16-8)	mg/kg	儀/質譜儀檢測. / With reference to IEC 62321-8 (2017). Analysis was performed by GC/MS.	50	n. d.
鄰苯二甲酸二正己酯 / DNHP (Di-n-hexyl phthalate) (CAS No.: 84-75-3)	mg/kg	per formed by GC/MS.	50	n. d.
鄰苯二甲酸二正壬酯 / DNNP (Di-n-nonyl phthalate) (DNP) (CAS No.: 84-76-4)	mg/kg		50	n. d.
六溴環十二烷及所有主要被辨別出的異構物 / Hexabromocyclododecane (HBCDD) and all major diastereoisomers identified (α - HBCDD, β - HBCDD, γ - HBCDD) (CAS No.: 25637-99-4 and 3194-55-6 (134237-51-7, 134237-50-6, 134237-52-8))	mg/kg	參考IEC 62321 (2008),以氣相層析/ 質譜儀檢測. / With reference to IEC 62321 (2008). Analysis was performed by GC/MS.	5	n. d.
鹵素 / Halogen				
鹵素(氟)/ Halogen-Fluorine (F) (CAS No.: 14762-94-8)	mg/kg	参考BS EN 14582 (2016),以離子層析 儀分析. / With reference to BS EN 14582 (2016). Analysis was performed by IC.	50	n. d.
鹵素(氣)/ Halogen-Chlorine (C1) (CAS No.: 22537-15-1)	mg/kg		50	n. d.
鹵素(溴)/ Halogen-Bromine (Br) (CAS No.: 10097-32-2)	mg/kg		50	n. d.
鹵素(碘)/ Halogen-Iodine(I)(CAS No.: 14362-44-8)	mg/kg		50	n. d.



號碼(No.): CE/2017/55480

日期(Date): 2017/06/01

頁數(Page): 6 of 14

Test Report

鴻星電子股份有限公司

HOSONIC ELECTRONIC CO., LTD.

新北市樹林區俊英街84巷23-1號

NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

測試項目 (Test Items)	單位 (Unit)	測試方法 (Method)	方法偵測 極限值 (MDL)	結果 (Result) No.1
全氟辛烷磺酸 / Perfluorooctane sulfonates (PFOS-Acid, Metal Salt, Amide)	mg/kg	參考US EPA 3550C (2007),以液相層析/質譜儀檢測. / With reference to US EPA 3550C (2007). Analysis was performed by LC/MS.	10	n. d.
全氟辛酸 / PFOA (CAS No.: 335-67-1)	mg/kg	参考US EPA 3550C (2007),以液相層析/質譜儀檢測. / With reference to US EPA 3550C (2007). Analysis was performed by LC/MS.	10	n. d.

備註(Note):

- 1. mg/kg = ppm ; 0.1wt% = 1000ppm
- 2. n.d. = Not Detected (未檢出)
- 3. MDL = Method Detection Limit (方法偵測極限值)
- 4. "-" = Not Regulated (無規格值)
- 5. **(♦**):

若鉻含量小於六價鉻之方法偵測極限值,則六價鉻為n.d.,不須再測試六價鉻。

The result of Cr(VI) is "n.d." as the result of Chromium (Cr) is less than the MDL of Cr(VI), and confirmation test of Cr(VI) is not required.

若鉻含量未小於六價鉻之方法偵測極限值,需進行六價鉻測試。

If the Chromium (Cr) content is not less than the MDL of Cr(VI), confirmation test of Cr(VI) is required.

6. 樣品的測試是基於申請人要求混合測試,報告中的混合測試結果不代表其中個別單一材質的含量. (The samples was/were analyzed on behalf of the applicant as mixing sample in one testing. The above results was/were only given as the informality value.)

PFOS参考資訊(Reference Information): 持久性有機污染物 POPs - (EU) 757/2010

PFOS濃度在物質或製備中不得超過0.001%(10ppm),在半成品、成品或零部件中不得超過0.1%(1000ppm),在紡織品或塗 層材料中不得超過1µg/m²。

(Outlawing PFOS as substances or preparations in concentrations above 0.001% (10ppm), in semi-finished products or articles or parts at a level above 0.1%(1000ppm), in textiles or other coated materials above $1\mu g/m^2$.)



Test Report

日期(Date): 2017/06/01 號碼(No.): CE/2017/55480

頁數(Page): 7 of 14

鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號


NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

重金屬流程圖 / Analytical flow chart of Heavy Metal

根據以下的流程圖之條件,樣品已完全溶解。(六價鉻測試方法除外)

These samples were dissolved totally by pre-conditioning method according to below flow chart. (Cr^{6+} test method excluded)

- 測試人員:王志瑋 / Technician: JR Wang
- 測試負責人:張啟興 / Supervisor: Troy Chang





號碼(No.): CE/2017/55480

日期(Date): 2017/06/01

頁數(Page): 8 of 14

Test Report

鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號

NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN




根據以下的流程圖之條件,樣品已完全溶解。 / These samples were dissolved totally by pre-conditioning method according to below flow chart.

測試人員:王志瑋 / Technician: JR Wang

測試負責人:張啟興 / Supervisor: Troy Chang

元素以 ICP-AES 分析的消化流程圖 (Flow Chart of digestion for the elements analysis performed by ICP-AES)



鋼,銅,鋁,焊錫 / Steel, copper, aluminum, solder	王水,硝酸,鹽酸,氫氟酸,雙氧水/
	Aqua regia, HNO ₃ , HCl, HF, H ₂ O ₂
玻璃 / Glass	硝酸,氫氟酸 / HNO ₃ /HF
金,鉑,鈀,陶瓷 / Gold, platinum, palladium, ceramic	王水 / Aqua regia
銀 / Silver	硝酸 / HNO ₃
塑膠 / Plastic	硫酸,雙氧水,硝酸,鹽酸 / H ₂ SO ₄ , H ₂ O ₂ , HNO ₃ , HCI
其他 / Others	加入適當的試劑至完全溶解 / Added appropriate reagent to total digestion



Test Report

新北市樹林區俊英街84巷23-1號

鴻星電子股份有限公司

號碼(No.): CE/2017/55480

NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN


HOSONIC ELECTRONIC CO., LTD.

日期(Date): 2017/06/01

全氟辛酸/全氟辛烷磺酸分析流程圖 / Analytical flow chart - PFOA/PFOS

測試人員:涂雅苓 / Technician: Yaling Tu

測試負責人:張啟興 / Supervisor: Troy Chang



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instruction, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced, except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

頁數(Page): 9 of 14



Test Report

鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號 NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

號碼(No.): CE/2017/55480




頁數(Page): 10 of 14

鹵素分析流程圖 / Analytical flow chart - Halogen

日期(Date): 2017/06/01

測試人員: 陳恩臻 / Technician: Rita Chen

測試負責人:張啟興 / Supervisor: Troy Chang





Test Report

日期(Date): 2017/06/01 號碼(No.): CE/2017/55480


頁數(Page): 11 of 14

鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號 NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

六溴環十二烷分析流程圖 / Analytical flow chart - HBCDD

測試人員:涂雅苓 / Technician: Yaling Tu

測試負責人:張啟興 / Supervisor: Troy Chang





Test Report

日期(Date): 2017/06/01 號碼(No.): CE/2017/55480

頁數(Page): 12 of 14


鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號 NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

可塑劑分析流程圖 / Analytical flow chart - Phthalate

測試人員:徐毓明 / Technician: Andy Shu

測試負責人:張啟興 / Supervisor: Troy Chang

【測試方法/Test method: IEC 62321-8】





Test Report

頁數(Page): 13 of 14

鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號 NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

號碼(No.): CE/2017/55480


多溴聯苯/多溴聯苯醚分析流程圖 / Analytical flow chart - PBB/PBDE

日期(Date): 2017/06/01

測試人員:涂雅苓 / Technician: Yaling Tu 測試負責人:張啟興 / Supervisor: Troy Chang

初次測試程序 / First testing process _ 選擇性篩檢程序 / Optional screen process ••••

確認程序 / Confirmation process ■ • ■ • •





Test Report

號碼(No.): CE/2017/55480 日期(Date): 2017/06/01

頁數(Page): 14 of 14


鴻星電子股份有限公司 HOSONIC ELECTRONIC CO., LTD. 新北市樹林區俊英街84巷23-1號 NO. 23-1, LN. 84, JUNYING ST., SHULIN DIST., NEW TAIPEI CITY 23863, TAIWAN

> * 照片中如有箭頭標示,則表示為實際檢測之樣品/部位. * (The tested sample / part is marked by an arrow if it's shown on the photo.)

> > CE/2017/55480



CE/2017/55480



** 報告結尾 (End of Report) **