

Calibration results

=====

Camera-system parameters:

cam0 (/cam0/image_raw):

type: <class 'aslam_cv.libaslam_cv_python.DistortedPinholeCameraGeometry'>

distortion: [0.06989963 -0.11571736 0.00095562 0.0022504] +- [0.00145222 0.00264645 0.00029363 0.00021859]

projection: [2720.51946242 2726.34873667 2066.0622728 1543.55527727] +- [2.23721675 2.12598585 2.1275132 2.59950858]

reprojection error: [0.000013, -0.000006] +- [1.141829, 0.869057]

Target configuration

=====

Type: checkerboard

Rows

Count: 8


Distance: 0.1 [m]

Cols



Count: 5

Distance: 0.1 [m]



cam0: estimated poses




cam0: polar error



cam0: azimuthal error



cam0: reprojection errors



Location of removed outlier corners

cam0

