


QDrone2 tracked 20 complete altitude steps during one recorded discharge

DEVELOPMENT OBSERVATIONS · original MPC · no recovery-failure labels

20 complete response windows; 1 incomplete (dotted line).



Repeated commands share one recording. Demand, voltage and elapsed time co-vary.

Observations: Borbolla-Burillo et al. · Zenodo 19464105 · CC BY 4.0