BCA Vehicle Appraisal Report

Grade 5


BJ10 HSN, PEUGEOT 308 SW

Registration: BJ10 HSN	Colour: BLUE	Appraised: 20/10/2025
Transmission: Automatic	Odometer: 82,721 miles	

Equipment

Air Conditioning	Parking Sensor(s)

Exterior condition



1. Bumper Rear; Cracked; Over 25mm
2. Door osf; Dented; Over 30mm
3. Qtr Panel nsr; Dented; Over 30mm
4. Qtr Panel osr; Dented; Over 30mm
5. Sill ns; Dented; With Paint Damage
6. Door nsr; Scratched; Over 25mm Thru Paint
7. Qtr Panel nsr; Scratched; Over 25mm Thru Paint
8. Wing osf; Scratched; Over 25mm Thru Paint
9. Bumper Front; Scratched; 25 to 100mm Thru Paint
10. Wheel Trim nsf; Scratched; Over 50mm
11. Wheel Trim nsr; Scratched; Over 50mm
12. Wheel Trim osf; Scratched; Over 50mm
13. Wheel Trim osr; Scratched; Over 50mm

Click to enlarge image


















Interior condition



1 Carpets Rear; Scuffed; Over 25mm