Vehicle Appraisal Report

Grade 3


BJ56 VHC, PEUGEOT 307

Registration: BJ56 VHC	Colour: GREY	Appraised: 26/10/2025
Transmission: Manual	Odometer: 89,306 miles	

Equipment


Air Conditioning	Alloy Wheels	Full Size Steel Spare

Exterior condition



1. Bonnet; Scratched; Over 25mm Thru Paint
2. Bumper Front; Scratched; Over 100mm Thru Paint
3. Qtr Panel nsr; Scratched; Rusted
4. C Post ns; Scratched; Over 25mm Thru Paint
5. C Post os; Scratched; Over 25mm Thru Paint
6. Bumper Front Moulding; Missing; Replace
7. Bumper Rear; Scratched; 25 to 100mm Thru Paint
8. Door Mirror Assy osf; Scratched (Painted); UpTo 25mm Thru Paint
9. Wheel nsf; Scratched; Up To 50mm
10. Wheel nsr; Scratched; Over 50mm
11. Wheel osf; Scratched; Over 50mm
12. Wheel osr; Scratched; Over 50mm

Click to enlarge image












Interior condition



1 Seat Back Cover osf; Scuffed; Over 25mm