BCA Vehicle Appraisal Report

Grade 4


CP08 HFO, HONDA JAZZ

Registration: CP08 HFO	Colour: SILVER	Appraised: 24/10/2025
Transmission: Manual	Odometer: 80,197 miles	

Equipment

Air Conditioning	Alloy Wheels	Space Saver Spare Wheel

Exterior condition



1. Door nsf; Dented; Over 30mm
2. Door nsr; Poor Previous Repair; Rippled UpTo 30%
3. Qtr Panel nsr; Dented; Over 30mm
4. Bonnet; Chipped; Multiple Chips
5. Bumper Rear; Scratched; Over 100mm Thru Paint
6. Door osr; Poor Previous Repair; Poor Colour
7. Screen Front; Chipped; Over 10mm
8. Bumper Front; Chipped; Multiple Chips
9. Wheel nsf; Scratched; Up To 50mm
10. Wheel nsr; Scratched; Over 50mm
11. Wheel osf; Scratched; Over 50mm
12. Wheel osr; Scratched; Over 50mm

Click to enlarge image
















Interior condition



1	Carpets Front; Torn; Over 10mm
2	Tailgate Pad; Broken; Replace
3	Rear Panel Trim Int; Scuffed; UpTo 25mm
4	Seat Base Cover nsf; Soiled; Light

Click to enlarge image



