BCA Vehicle Appraisal Report

Grade 5


DU55 BYJ, HYUNDAI GETZ

Registration: DU55 BYJ	Colour: RED	Appraised: 25/10/2025
Transmission: Automatic	Odometer: 61,374 miles	

Equipment

Alloy Wheels	Full Size Steel Spare

Exterior condition



1. Bumper Rear; Cracked; Over 25mm
2. Bonnet; Dented; Over 30mm
3. Door nsf; Dented; Over 30mm
4. Door nsr; Dented; Over 30mm
5. Door osr; Dented; Over 30mm
6. Qtr Panel nsr; Dented; With Paint Damage
7. Wing osf; Dented; Over 30mm
8. Bumper Front; Poor Previous Repair; Paint Flake
9. Qtr Panel osr; Rusted; Over 5mm
10. C Post ns; Scratched; Over 25mm Thru Paint
11. Moulding Tailgate; Scratched (Painted); Over 25mm Thru Paint
12. Door Mirror Assy nsf; Scratched (Painted); Over 25mm Thru Paint
13. Door Mirror Assy osf; Scratched (Painted); Over 25mm Thru Paint
14. Handle Outer nsf; Scratched (Painted); Over 25mm Thru Paint
15. Handle Outer osr; Scratched (Painted); Over 25mm Thru Paint
16. Wheel nsf; Scratched; Over 50mm
17. Wheel nsr; Scratched; Over 50mm

18 Wheel osf; Scratched; Over 50mm

19 Wheel osr; Scratched; Over 50mm

Click to enlarge image
























Interior condition



1. Door Pad osr; Scuffed; Over 25mm
2. Seat Base Cover osf; Scuffed; Over 25mm
3. Shelfload Cover Rear; Missing; Replace