Vehicle Appraisal Report

Grade 5


FV06 AFZ, AUDI A3 SPORTBACK

Registration: FV06 AFZ	Colour: BLUE	Appraised: 24/10/2025
Transmission: Auto Clutch	Odometer: 163,718 miles	

Equipment

Alloy Wheels	Climate Control	Parking Sensor(s)

Exterior condition



1. Bonnet; Dented; Over 30mm
2. Bumper Front; Dented; With Paint Damage
3. Door osr; Dented; Over 30mm
4. Qtr Panel osr; Dented; Over 30mm
5. Wing osf; Dented; Over 30mm
6. Bonnet; Chipped; Multiple Chips
7. Door nsf; Rusted; Over 5mm
8. Door osf; Rusted; Over 5mm
9. Door osr; Rusted; Over 5mm
10. Qtr Panel nsr; Rusted; Over 5mm
11. Qtr Panel osr; Rusted; Over 5mm
12. Roof; Scratched; Over 25mm Thru Paint
13. Sill os; Rusted; Over 5mm
14. Tailgate; Scratched; Over 25mm Thru Paint
15. Wing nsf; Rusted; Over 5mm
16. Door Mirror Assy nsf; Broken; Replace
17. Wiper Rear; Missing; Replace
18. Bumper Rear; Scratched; 25 to 100mm Thru Paint

19 Wheel nsf; Scratched; Over 50mm

20 Wheel nsr; Corroded; Light

21 Wheel osf; Scratched; Over 50mm

22 Wheel osr; Scratched; Over 50mm

Click to enlarge image


































Interior condition



1. Carpets Front; Torn; Over 10mm
2. Headrest Assy Rear Seat Centr; Missing; Replace
3. Switches And Controls; Broken; Replace
4. Tailgate Pad; Scuffed; UpTo 25mm

Click to enlarge image





