BCA Vehicle Appraisal Report

Grade 4


GL57 HVV, MINI COOPER

Registration: GL57 HVV	Colour: SILVER	Appraised: 20/10/2025
Transmission: Manual	Odometer: 69,188 miles	

Equipment


Air Conditioning	Alloy Wheels	Leather Trim
Parking Sensor(s)		

Exterior condition



1. Bonnet; Scratched; Over 25mm Thru Paint
2. Bumper Front; Scratched; Over 100mm Thru Paint
3. Door nsf; Scratched; Over 25mm Thru Paint
4. Qtr Panel osr; Scratched; Over 25mm Thru Paint
5. B Post os; Scratched; Over 25mm Thru Paint
6. Wheel nsf; Scratched; Over 50mm
7. Wheel nsr; Scratched; Over 50mm
8. Wheel osf; Scratched; Up To 50mm
9. Wheel osr; Scratched; Up To 50mm

Click to enlarge image












Interior condition



1. Door Pad osf; Torn; Over 10mm
2. Seat Back Cover osf; Torn; Over 3mm
3. Fascia Trim; Damaged; Replace
4. Switches And Controls; Broken; Replace
5. Door Pad nsf; Scuffed; UpTo 25mm

Click to enlarge image







