BCA Vehicle Appraisal Report

Grade 4


GN13 VWE, VAUXHALL MERIVA

Registration: GN13 VWE	Colour: WHITE	Appraised: 22/10/2025
Transmission: Manual	Odometer: 119,585 miles	

Equipment

17" Alloy Wheels	Air Conditioning	Half Leather Trim
Panoramic Roof	Privacy Glass	

Exterior condition



1. Bumper Rear; Dented; With Paint Damage
2. Door osf; Dented; Over 30mm
3. Door nsr; Poor Previous Repair; Poor Paint
4. Qtr Panel nsr; Scratched; Over 25mm Thru Paint
5. Bumper Front; Chipped; Multiple Chips
6. Wheel nsf; Scratched; Over 50mm
7. Wheel nsr; Scratched; Over 50mm
8. Wheel osf; Scratched; Over 50mm
9. Wheel osr; Scratched; Over 50mm
10. General Interior; Buyer Advisory; Report Only

Click to enlarge image












Interior condition



1 Seat Base Cover osf; Torn; Over 3mm

2 Fascia Trim; Damaged; Replace

3 Shelfload Cover Rear; Missing; Replace

Click to enlarge image



