Vehicle Appraisal Report

Grade 4


HG57 TMY, MERCEDES-BENZ A170

Registration: HG57 TMY	Colour: BLUE	Appraised: 24/10/2025
Transmission: Manual	Odometer: 72,537 miles	

Equipment

Air Conditioning	Alloy Wheels	Half Leather Trim
Parking Sensor(s)	Space Saver Spare Wheel	

Exterior condition



1. Bumper Rear; Dented; With Paint Damage
2. Door nsr; Dented; With Paint Damage
3. Qtr Panel nsr; Dented; With Paint Damage
4. Qtr Panel osr; Dented; Over 30mm
5. Bumper Front; Scratched; Over 100mm Thru Paint
6. Bumper Rear; Scratched; Over 100mm Thru Paint
7. B Post ns; Scratched; Over 25mm Thru Paint
8. B Post os; Scratched; Over 25mm Thru Paint
9. C Post ns; Scratched; Over 25mm Thru Paint
10. Bumper Rear; Insecure; Action Required
11. Aperture Seal osf; Broken; Replace
12. Door Moulding osr; Broken; Replace
13. Wheel nsf; Scratched; Over 50mm
14. Wheel nsr; Scratched; Up To 50mm
15. Wheel osf; Scratched; Over 50mm
16. Wheel osr; Scratched; Over 50mm

Click to enlarge image






















Interior condition



1 Seat Base Cover osf; Torn; Over 3mm

Click to enlarge image

