BCA Vehicle Appraisal Report

Grade 5


HN15 BYS, RENAULT CAPTUR

Registration: HN15 BYS	Colour: BLACK	Appraised: 26/10/2025
Transmission: Manual	Odometer: 179,256 miles	

Equipment

17" Alloy Wheels	Climate Control	Navigation HDD

Exterior condition



1. Door nsr; Dented; Over 30% Of Panel
2. Roof; Dented; Over 30mm
3. Bonnet; Chipped; Multiple Chips
4. Bumper Rear; Scratched; Over 100mm Thru Paint
5. Tailgate Glass; Scratched; Over 30mm
6. Bumper Front; Insecure; Action Required
7. Door Moulding nsr; Missing; Replace
8. Moulding Tailgate; Broken; Replace
9. Qtr Panel Arch Extension ns; Missing; Replace
10. Aerial; Missing; Replace
11. Bumper Front; Chipped; Multiple Chips
12. Bumper Rear Moulding; Scuffed (Unpainted); Over 100mm
13. Wheel nsf; Corroded; Light
14. Wheel nsr; Corroded; Light
15. Wheel osf; Corroded; Light
16. Wheel osr; Corroded; Light


Click to enlarge image




















Interior condition



1. Door Pad nsf; Scuffed; Over 25mm
2. Door Pad nsr; Scuffed; Over 25mm
3. Door Pad osf; Scuffed; Over 25mm
4. Door Pad osr; Scuffed; Over 25mm
5. Tailgate Pad; Scuffed; Over 25mm