BCA Vehicle Appraisal Report

Grade 5


HN59 AAO, MAZDA 3

Registration: HN59 AAO	Colour: GREY	Appraised: 26/10/2025
Transmission: Manual	Odometer: 157,076 miles	

Equipment

17" Alloy Wheels	Climate Control	Leather Trim
Parking Sensor(s)	Privacy Glass	


Exterior condition



1. Door osr; Dented; Over 30mm
2. Qtr Panel nsr; Dented; With Paint Damage
3. Tailgate; Dented; Over 30mm
4. Wing osf; Dented; Over 30mm
5. Bonnet; Chipped; Multiple Chips
6. Bumper Front; Scratched; Over 100mm Thru Paint
7. Qtr Panel osr; Rusted; Over 5mm
8. Roof; Rusted; Over 5mm
9. Screen Front; Chipped; UpTo 10mm
10. Bumper Rear; Scratched; 25 to 100mm Thru Paint
11. Wheel nsf; Scratched; Over 50mm
12. Wheel nsr; Scratched; Up To 50mm
13. Wheel osf; Scratched; Over 50mm
14. Wheel osr; Scratched; Over 50mm

Click to enlarge image




















Interior condition



1. Seat Base Cover osf; Torn; Over 3mm
2. Switches And Controls; Broken; Replace
3. Switches And Controls; Broken; Replace
4. Door Pad osf; Scuffed; Over 25mm
5. Door Pad osr; Scuffed; Over 25mm
6. Seat Back Cover nsf; Scuffed; UpTo 25mm
7. Seat Back Cover osf; Scuffed; Over 25mm
8. Shelfload Cover Rear; Missing; Replace
9. Tailgate Pad; Scuffed; Over 25mm

Click to enlarge image





