# BCA Vehicle Appraisal Report

Grade 4


## KFZ 8351, HYUNDAI I20

| | | |
|---|---|---|
| Registration: KFZ 8351 | Colour: GREY | Appraised: 24/10/2025 |
| Transmission: Manual | Odometer: 85,659 miles | |

## Equipment

| | |
|---|---|
| Air Conditioning | Alloy Wheels |

## Exterior condition




1. Bumper Rear; Cracked; Over 25mm
2. Roof; Dented; Over 30mm
3. Qtr Panel nsr; Rusted; Over 5mm
4. Tailgate; Rusted; Over 5mm
5. B Post os; Scratched; UpTo 25mm Thru Paint
6. B Post os; Dented; Between 10mm + 30mm
7. Bumper Front; Scratched; 25 to 100mm Thru Paint
8. C Post os; Scratched; UpTo 25mm Thru Paint
9. Door Mirror Assy nsf; Scratched (Painted); UpTo 25mm Thru Paint
10. Door nsf; Dented; Between 10mm + 30mm
11. Door nsr; Scratched; UpTo 25mm Thru Paint
12. Door osf; Dented; Between 10mm + 30mm
13. Door osf; Chipped; Edge Chip
14. Door osr; Scratched; UpTo 25mm Thru Paint
15. Qtr Panel osr; Dented; Between 10mm + 30mm
16. Wheel nsf; Scratched; Over 50mm
17. Wheel nsr; Scratched; Over 50mm

18 Wheel osf; Scratched; Over 50mm

19 Wheel osr; Scratched; Over 50mm

20 Wing nsf; Scratched; UpTo 25mm Thru Paint

21 Wing osf; Scratched; UpTo 25mm Thru Paint

Click to enlarge image













## Interior condition

