BCA Vehicle Appraisal Report

Grade 5


KM63 PUO, VAUXHALL ASTRA TOURER

Registration: KM63 PUO	Colour: BLUE	Appraised: 23/10/2025
Transmission: Automatic	Odometer: 141,584 miles	

Equipment

Air Conditioning	Alloy Wheels


Exterior condition



1. Door nsr; Dented; With Paint Damage
2. Qtr Panel nsr; Dented; With Paint Damage
3. Tailgate; Dented; Over 30mm
4. Bonnet; Chipped; Multiple Chips
5. Bumper Front; Poor Previous Repair; Poor Colour
6. Bumper Rear; Poor Previous Repair; Poor Colour
7. Door osf; Poor Previous Repair; Poor Paint
8. Door osr; Chipped; Multiple Chips
9. Roof; Poor Previous Repair; Paint Flake
10. Screen Front; Cracked; Replace
11. Wing nsf; Chipped; Multiple Chips
12. Wing osf; Chipped; Multiple Chips
13. Aperture Seal osf; Broken; Replace
14. Bumper Front Grill; Broken; Replace
15. Wheel nsf; Scratched; Over 50mm
16. Wheel nsr; Scratched; Over 50mm
17. Wheel osf; Scratched; Over 50mm
18. Wheel osr; Scratched; Over 50mm

Click to enlarge image
































Interior condition



1 Tailgate Pad; Scuffed; Over 25mm

Click to enlarge image

