BCA Vehicle Appraisal Report

Grade 5


KU60 JXJ, BMW 118I

Registration: KU60 JXJ	Colour: BLUE	Appraised: 25/10/2025
Transmission: Auto/Manual Mode	Odometer: 107,086 miles	

Equipment

Alloy Wheels	Climate Control	Leather Trim
Parking Sensor(s)		

Exterior condition



1. Bumper Rear; Cracked; Over 25mm
2. Qtr Panel nsr; Dented; Over 30mm
3. Roof; Dented; Over 30mm
4. Tailgate; Dented; Over 30mm
5. Bonnet; Chipped; Multiple Chips
6. Wing osf; Scratched; Over 25mm Thru Paint
7. Aperture Seal osf; Broken; Replace
8. Bumper Front; Scratched; 25 to 100mm Thru Paint
9. Parking Sensor Rear; Missing; Replace
10. Rear TowEye Cvr; Missing; Replace
11. Wheel nsf; Scratched; Over 50mm
12. Wheel nsr; Scratched; Over 50mm
13. Wheel osf; Scratched; Over 50mm
14. Wheel osr; Scratched; Over 50mm
15. General Interior; Buyer Advisory; Report Only

Click to enlarge image
















Interior condition



1. Seat Base Cover osf; Torn; Over 3mm
2. Seat Back Cover nsf; Scuffed; Over 25mm
3. Seat Back Cover osf; Scuffed; Over 25mm
4. Tailgate Pad; Scuffed; Over 25mm

Click to enlarge image

