
Vehicle Appraisal Report

Grade 2

LD02 RZH, SUZUKI GRAND VITARA

Registration: LD02 RZH	Colour: SILVER	Appraised: 17/10/2025
Transmission: Automatic	Odometer: 107,786 miles	

Exterior condition




1. Bumper Front; Poor Previous Repair; Paint Flake
2. C Post os; Scratched; Over 25mm Thru Paint
3. Bumper Rear; Scratched; 25 to 100mm Thru Paint
4. Wheel nsf; Corroded; Light
5. Wheel nsr; Corroded; Light
6. Wheel osf; Corroded; Light
7. Wheel osr; Corroded; Light

Click to enlarge image





Interior condition



1 Shelfload Cover Rear; Missing; Replace

2 Tailgate Pad; Scuffed; Over 25mm