BCA Vehicle Appraisal Report

Grade 3


LG10 YZW, HYUNDAI I20

Registration: LG10 YZW	Colour: RED	Appraised: 22/10/2025
Transmission: Manual	Odometer: 92,932 miles	

Equipment

Air Conditioning	Alloy Wheels

Exterior condition



1. Bumper Rear; Dented; With Paint Damage
2. Bumper Front; Scratched; Over 100mm Thru Paint
3. Bumper Rear; Poor Previous Repair; Paint Flake
4. Headlamp ns; Broken; Replace
5. Lamp nsr; Broken; Replace
6. Lamp nsr; Broken; Replace
7. Door Mirror Assy nsf; Scratched (Painted); Over 25mm Thru Paint
8. Moulding Tailgate; Scratched (Painted); Over 25mm Thru Paint
9. Door Mirror Assy osf; Scratched (Painted); Over 25mm Thru Paint
10. Door Mirror Assy osf; Scratched (Painted); Over 25mm Thru Paint
11. Wheel nsf; Scratched; Over 50mm
12. Wheel nsr; Scratched; Over 50mm
13. Wheel osf; Scratched; Over 50mm
14. Wheel osr; Scratched; Over 50mm
15. Wheel Trim osr; Missing; Replace
16. General Exterior; Decals Fitted; Body Transfers

17 General Interior; Soiled; Light

18 General Interior; Buyer Advisory; Report Only

19 General Interior; Soiled; Light

20 General Interior; Buyer Advisory; Report Only

Click to enlarge image
























Interior condition



1 Fascia Panel; Scuffed; UpTo 25mm

2 Fascia Trim; Damaged; Replace

3 Door Pad osr; Scuffed; Over 25mm

4 Glove Box Lid; Scuffed; Over 25mm

5 Seat Base Cover osf; Scuffed; Over 25mm

6 Door Pad nsr; Soiled; Light

7 Door Pad osf; Soiled; Light

Click to enlarge image







