BCA Vehicle Appraisal Report

Grade 4


LT57 HJZ, VAUXHALL ASTRA

Registration: LT57 HJZ	Colour: BLUE	Appraised: 22/10/2025
Transmission: Manual	Odometer: 93,819 miles	

Equipment

18" Alloy Wheels	Climate Control	Leather Trim
Privacy Glass	Space Saver Spare Wheel	

Exterior condition




1. Tailgate; Dented; Over 30mm
2. Wing nsf; Dented; Over 30mm
3. Bumper Front; Scratched; Over 100mm Thru Paint
4. Bumper Rear; Scratched; Over 100mm Thru Paint
5. Door nsf; Scratched; Over 25mm Thru Paint
6. Qtr Panel nsr; Scratched; Over 25mm Thru Paint
7. Wing nsf; Poor Previous Repair; Paint Flake
8. Bumper Rear; Scratched; 25 to 100mm Thru Paint
9. Moulding osf Wing; Scuffed (Unpainted); Over 100mm
10. Tailgate Aperture Seal; Broken; Replace
11. Wheel nsf; Scratched; Over 50mm
12. Wheel nsr; Scratched; Over 50mm
13. Wheel osf; Scratched; Over 50mm
14. Wheel osr; Scratched; Over 50mm
15. General Interior; Decals Fitted; Body Transfers
16. General Interior; Decals Fitted; Body Transfers

Click to enlarge image
























Interior condition



1. Fascia Trim; Damaged; Replace
2. Door Pad osf; Scuffed; Over 25mm
3. Seat Back Cover nsf; Scuffed; UpTo 25mm
4. Seat Back Cover osf; Scuffed; Over 25mm

Click to enlarge image

