BCA Vehicle Appraisal Report

Grade 5


ML09 WJD, FORD C-MAX

Registration: ML09 WJD	Colour: BLUE	Appraised: 18/10/2025
Transmission: Automatic	Odometer: 96,964 miles	

Equipment

17" Alloy Wheels	Air Conditioning	Full Size Steel Spare

Exterior condition



1. Door osr; Poor Previous Repair; Rippled UpTo 30%
2. Qtr Panel osr; Dented; Over 30mm
3. Tailgate; Dented; Over 30mm
4. Bonnet; Poor Previous Repair; Poor Paint
5. Door nsf; Chipped; Over 5mm
6. Door osf; Poor Previous Repair; Poor Paint
7. Qtr Panel nsr; Scratched; Over 25mm Thru Paint
8. Roof; Poor Previous Repair; Paint Flake
9. Screen Front; Cracked; Replace
10. Sill os; Rusted; Over 5mm
11. Moulding osf Wing; Broken; Replace
12. Bumper Front; Scratched; 25 to 100mm Thru Paint
13. Bumper Rear; Scratched; 25 to 100mm Thru Paint
14. Wheel nsf; Scratched; Over 50mm
15. Wheel osf; Scratched; Over 50mm
16. General Interior; Buyer Advisory; Report Only

Click to enlarge image


























Interior condition



1 Fascia Trim; Damaged; Replace

2 Door Pad osr; Scuffed; UpTo 25mm

3 Shelfload Cover Rear; Missing; Replace

4 Tailgate Pad; Scuffed; UpTo 25mm

5 Seat Base Cover osr; Soiled; Light

Click to enlarge image



