Vehicle Appraisal Report

Grade 3


MW54 KLK, MERCEDES-BENZ C200

Registration: MW54 KLK	Colour: BLUE	Appraised: 21/10/2025
Transmission: Auto/Manual Mode	Odometer: 89,866 miles	

Equipment

17" Alloy Wheels	Climate Control	Leather Trim
Parking Sensor(s)		

Exterior condition



1. Bonnet; Chipped; Multiple Chips
2. Qtr Panel nsr; Rusted; Over 5mm
3. Qtr Panel osr; Rusted; Over 5mm
4. Bumper Front; Scratched; 25 to 100mm Thru Paint
5. Wheel nsf; Scratched; Over 50mm
6. Wheel nsr; Scratched; Over 50mm
7. Wheel osf; Scratched; Over 50mm
8. Wheel osr; Scratched; Over 50mm


Click to enlarge image







Interior condition



1 Seat Base Cover osf; Torn; Over 3mm

Click to enlarge image

