BCA Vehicle Appraisal Report

Grade 4


NU10 GPF, RENAULT MEGANE

Registration: NU10 GPF	Colour: SILVER	Appraised: 24/10/2025
Transmission: Manual	Odometer: 112,216 miles	

Equipment

Air Conditioning	Alloy Wheels

Exterior condition



1. Sill os; Dented; Over 30mm
2. Bonnet; Poor Previous Repair; Paint Flake
3. Bumper Front; Poor Previous Repair; Paint Flake
4. Door nsf; Scratched; Over 25mm Thru Paint
5. Qtr Panel nsr; Scratched; Over 25mm Thru Paint
6. Bumper Rear; Scratched; 25 to 100mm Thru Paint
7. Door Moulding osf; Scratched (Painted); Over 25mm Thru Paint
8. Door Mirror Assy osf; Scratched (Painted); UpTo 25mm Thru Paint
9. Wheel nsf; Scratched; Over 50mm
10. Wheel nsr; Scratched; Over 50mm
11. Wheel osf; Scratched; Over 50mm
12. Wheel osr; Scratched; Over 50mm

Click to enlarge image
















Interior condition



1. Headrest Assy Rear Seat os; Missing; Replace
2. Qtr Panel Trim ns; Scuffed; Over 25mm
3. Qtr Panel Trim os; Scuffed; Over 25mm
4. Seat Back Cover osf; Scuffed; UpTo 25mm
5. Tailgate Pad; Scuffed; Over 25mm

Click to enlarge image



