BCA Vehicle Appraisal Report

Grade 3


OY58 BAA, MERCEDES-BENZ CLC 220

Registration: OY58 BAA	Colour: SILVER	Appraised: 23/10/2025
Transmission: Auto/Manual Mode	Odometer: 130,456 miles	

Equipment

Alloy Wheels	Climate Control	Leather Trim
Parking Sensor(s)	Space Saver Spare Wheel	

Exterior condition



1. Bonnet; Dented; Over 30mm
2. Roof; Dented; Over 30mm
3. Bonnet; Rusted; Over 5mm
4. Qtr Panel osr; Scratched; Over 25mm Thru Paint
5. Bumper Front; Scratched; 25 to 100mm Thru Paint
6. Wheel nsf; Scratched; Over 50mm
7. Wheel nsr; Scratched; Over 50mm
8. Wheel osf; Scratched; Over 50mm
9. Wheel osr; Scratched; Over 50mm

Click to enlarge image










Interior condition



1 Seat Back Cover osf; Scuffed; Over 25mm