Vehicle Appraisal Report

Grade 4


PJ09 AEE, MINI COOPER

Registration: PJ09 AEE	Colour: RED	Appraised: 22/10/2025
Transmission: Manual	Odometer: 89,877 miles	

Equipment

17" Alloy Wheels	Air Conditioning	Half Leather Trim

Exterior condition



1. Bonnet; Poor Previous Repair; Paint Flake
2. Bumper Front; Poor Previous Repair; Paint Flake
3. Door nsf; Poor Previous Repair; Paint Flake
4. Door osf; Poor Previous Repair; Poor Paint
5. Qtr Panel osr; Poor Previous Repair; Paint Flake
6. Tailgate; Poor Previous Repair; Paint Flake
7. Wing osf; Poor Previous Repair; Poor Paint
8. Bumper Front Moulding; Broken; Replace
9. Wheel nsf; Scratched; Up To 50mm
10. Wheel nsr; Scratched; Up To 50mm
11. Wheel osf; Scratched; Over 50mm
12. Wheel osr; Scratched; Over 50mm
13. General Exterior; Buyer Advisory; Report Only
14. Tyre nsr; Damaged; Replace

Click to enlarge image






















Interior condition



1 Door Pad osf; Torn; Over 10mm

2 Shelfload Cover Rear; Damaged; Replace

Click to enlarge image



