BCA Vehicle Appraisal Report

Grade 5


RJ04 NKZ, BMW X3

Registration: RJ04 NKZ	Colour: RED	Appraised: 25/10/2025
Transmission: Automatic	Odometer: 103,488 miles	

Equipment

Alloy Wheels	Climate Control	Leather Trim
Parking Sensor(s)	Privacy Glass	

Exterior condition



1. Bumper Front; Cracked; Over 25mm
2. Bonnet; Dented; With Paint Damage
3. Wing nsf; Dented; Over 30mm
4. Bumper Rear; Scratched; Over 100mm Thru Paint
5. Bumper Front; Insecure; Action Required
6. Screen Front; Chipped; UpTo 10mm
7. Badgedecal Rear; Broken; Replace
8. Sill Panel Trim ns; Scratched (Painted); Over 25mm Thru Paint
9. Sill Panel Trim os; Scratched (Painted); Over 25mm Thru Paint
10. Wheel nsf; Scratched; Over 50mm
11. Wheel nsr; Scratched; Over 50mm
12. Wheel osf; Scratched; Up To 50mm
13. Wheel Trim osr; Scratched; Up To 50mm
14. Wing Front Arch Extension os; Broken; Replace

Click to enlarge image














Interior condition



1. Carpets Front; Burn; Between 3mm + 10mm
2. Steering Wheel; Damaged; Replace
3. Fascia Trim; Damaged; Replace
4. Shelfload Cover Rear; Damaged; Replace
5. Tailgate Pad; Scuffed; Over 25mm

Click to enlarge image

