Vehicle Appraisal Report

Grade 3


ST09 AFJ, VOLVO C30

Registration: ST09 AFJ	Colour: BLUE	Appraised: 21/10/2025
Transmission: Manual	Odometer: -	

Equipment

17" Alloy Wheels	Climate Control	Leather Trim
Parking Sensor(s)		

Exterior condition




1. Bumper Rear; Dented; With Paint Damage
2. Bumper Front; Scratched; Over 100mm Thru Paint
3. Bumper Front; Scratched; 25 to 100mm Thru Paint
4. Door Mirror Assy osf; Scratched (Painted); Over 25mm Thru Paint
5. Grille Front; Scratched (Painted); Over 25mm Thru Paint
6. Moulding nsf Wing; Scratched (Painted); Over 25mm Thru Paint
7. Wheel nsf; Scratched; Over 50mm
8. Wheel nsr; Scratched; Over 50mm
9. Wheel osf; Scratched; Over 50mm
10. Wheel osr; Scratched; Over 50mm

Click to enlarge image





Interior condition



1. Seat Base Cover osf; Torn; Over 3mm
2. Fascia Trim; Damaged; Replace
3. Seat Back Cover osf; Scuffed; Over 25mm
4. Seat Back Cover nsf; Scuffed; Over 25mm
5. Seat Base Cover nsf; Scuffed; Over 25mm

Click to enlarge image





