BCA Vehicle Appraisal Report

Grade 5


SV63 TLN, CITROEN C4 PICASSO

Registration: SV63 TLN	Colour: BLUE	Appraised: 24/10/2025
Transmission: Auto Clutch	Odometer: 262,478 miles	

Equipment

17" Alloy Wheels	Climate Control	Navigation CD
Parking Sensor(s)		

Exterior condition



1. Door nsr; Dented; Over 30mm
2. Qtr Panel nsr; Dented; Over 30mm
3. Sill os; Dented; With Paint Damage
4. Bonnet; Chipped; Multiple Chips
5. Bumper Front; Poor Previous Repair; Poor Colour
6. Bumper Rear; Poor Previous Repair; Paint Flake
7. Door nsf; Poor Previous Repair; Paint Flake
8. Door osf; Rusted; Over 5mm
9. Sill ns; Rusted; Over 5mm
10. Sill os; Rusted; Over 5mm
11. Tailgate; Poor Previous Repair; Poor Paint
12. Wing nsf; Rusted; Over 5mm
13. Wing osf; Rusted; Over 5mm
14. B Post os; Dented; With Paint Damage
15. A Post ns; Rusted; Over 5mm
16. A Post os; Rusted; Over 5mm

17 Door Mirror Assy nsf; Scratched (Painted); Over 25mm Thru Paint

18 Wheel nsf; Corroded; Light

19 Wheel nsr; Corroded; Light

20 Wheel osf; Corroded; Light

21 Wheel osr; Corroded; Light

22 Wheel Trim nsf; Missing; Replace

23 Wheel Trim nsr; Missing; Replace

24 Wheel Trim osf; Missing; Replace

25 Wheel Trim osr; Missing; Replace

26 General Exterior; Buyer Advisory; Report Only

Click to enlarge image







































Interior condition



1. Seat Base Cover osf; Torn; Over 3mm
2. Air Vents osf; Damaged; Replace
3. Switches And Controls; Broken; Replace
4. Air Vents nsf; Damaged; Replace

Click to enlarge image

