Vehicle Appraisal Report

Grade 5


WL57 EYU, HONDA CIVIC

Registration: WL57 EYU	Colour: SILVER	Appraised: 24/10/2025
Transmission: Manual	Odometer: 93,164 miles	

Equipment

Alloy Wheels	Climate Control	Panoramic Roof
Privacy Glass	Space Saver Spare Wheel	

Exterior condition



1. Bonnet; Dented; Over 30mm
2. Bumper Front; Dented; With Paint Damage
3. Door osf; Dented; Over 30mm
4. Qtr Panel nsr; Dented; With Paint Damage
5. Wing osf; Dented; Over 30mm
6. Bumper Rear; Scratched; Over 100mm Thru Paint
7. Qtr Panel osr; Rusted; Over 5mm
8. Door Mirror Assy nsf; Broken; Replace
9. Door Mirror Assy osf; Broken; Replace
10. Fogdriving Lamp nsf; Broken; Replace
11. Bumper Front Moulding; Broken; Replace
12. Front TowEye Cvr; Missing; Replace
13. Wheel nsf; Scratched; Over 50mm
14. Wheel nsr; Scratched; Over 50mm
15. Wheel osf; Scratched; Over 50mm
16. Wheel osr; Scratched; Up To 50mm

Click to enlarge image




















Interior condition



1. Door Pad osf; Scuffed; Over 25mm
2. Rear Panel Trim Int; Scuffed; Over 25mm
3. Seat Back Cover nsf; Scuffed; Over 25mm
4. Seat Back Cover osf; Scuffed; Over 25mm
5. Tailgate Pad; Scuffed; Over 25mm