BCA Vehicle Appraisal Report

Grade 5


YA08 GMV, RENAULT MEGANE

Registration: YA08 GMV	Colour: BLUE	Appraised: 23/10/2025
Transmission: Manual	Odometer: 90,805 miles	

Equipment

Air Conditioning	Alloy Wheels

Exterior condition



1. Bumper Front; Poor Previous Repair; Poor Paint
2. Bumper Rear; Poor Previous Repair; Poor Paint
3. Door nsr; Poor Previous Repair; Poor Paint
4. Door osr; Poor Previous Repair; Poor Paint
5. Qtr Panel nsr; Poor Previous Repair; Poor Paint
6. Roof; Poor Previous Repair; Paint Flake
7. Tailgate; Poor Previous Repair; Poor Paint
8. A Post ns; Poor Previous Repair; Poor Paint
9. A Post os; Poor Previous Repair; Poor Paint
10. B Post os; Scratched; Over 25mm Thru Paint
11. Fuel Flap; Poor Previous Repair; Poor Paint
12. Lamp osr; Broken; Replace
13. Bumper Front Moulding; Scratched (Painted); Over 25mm Thru Paint
14. Door Mirror Assy nsf; Scratched (Painted); Over 25mm Thru Paint
15. Wheel nsf; Scratched; Over 50mm
16. Wheel osf; Scratched; Over 50mm
17. Wheel osr; Scratched; Over 50mm

Click to enlarge image


























Interior condition



1. Door Pad nsr; Torn; Between 3mm + 10mm
2. Door Pad osf; Torn; Between 3mm + 10mm
3. Seat Back Cover osf; Torn; Over 3mm
4. Fascia Trim; Damaged; Replace

Click to enlarge image







