BCA Vehicle Appraisal Report

Grade 3


YS08 ZRY, PEUGEOT 107

Registration: YS08 ZRY	Colour: SILVER	Appraised: 23/10/2025
Transmission: Auto Clutch	Odometer: 65,025 miles	

Equipment

Space Saver Spare Wheel

Exterior condition



1. Bumper Front; Dented; With Paint Damage
2. Qtr Panel osr; Scratched; Over 25mm Thru Paint
3. Sill os; Rusted; Over 5mm
4. Bumper Front; Insecure; Action Required
5. Bumper Rear; Insecure; Action Required
6. Aperture Seal nsf; Broken; Replace
7. Bumper Rear; Scratched; 25 to 100mm Thru Paint
8. Wheel Trim nsf; Scratched; Over 50mm
9. Wheel Trim nsr; Scratched; Over 50mm
10. Wheel Trim osf; Scratched; Over 50mm
11. Wheel Trim osr; Scratched; Over 50mm
12. General Interior; Soiled; Light

Click to enlarge image














Interior condition



1. Seat Back Cover osf; Torn; Over 3mm
2. Fascia Trim; Missing; Replace
3. Switches And Controls; Broken; Replace
4. Shelfload Cover Rear; Missing; Replace

Click to enlarge image





