Vehicle Appraisal Report

Grade 5


YT09 YGX, TOYOTA AVENSIS

Registration: YT09 YGX	Colour: SILVER	Appraised: 08/10/2025
Transmission: Manual	Odometer: 133,644 miles	

Equipment

17" Alloy Wheels	Climate Control	Navigation DVD

Exterior condition



1. Door nsf; Dented; Over 30mm
2. Door nsr; Dented; With Paint Damage
3. Door osr; Dented; Over 30mm
4. Qtr Panel nsr; Poor Previous Repair; Rippled UpTo 30%
5. Qtr Panel osr; Poor Previous Repair; Rippled UpTo 30%
6. Wing osf; Dented; Over 30mm
7. Bonnet; Chipped; Multiple Chips
8. Bumper Front; Scratched; Over 100mm Thru Paint
9. Bumper Front; Scratched; Over 100mm Thru Paint
10. Bumper Rear; Scratched; Over 100mm Thru Paint
11. Door nsr; Poor Previous Repair; Poor Paint
12. Door osf; Scratched; Over 25mm Thru Paint
13. Tailgate; Rusted; Over 5mm
14. C Post os; Scratched; Over 25mm Thru Paint
15. Lamp nsr; Broken; Replace
16. Wheel nsf; Scratched; Over 50mm
17. Wheel nsr; Scratched; Over 50mm
18. Wheel osf; Scratched; Over 50mm

19 Wheel osr; Scratched; Over 50mm

20 General Interior; Soiled; Light

21 Tyre osr; Punctured; Replace

Click to enlarge image
































Interior condition



1 Door Pad nsr; Torn; Over 10mm

2 Seat Back Cover osf; Scuffed; Over 25mm

3 Seat Base Cover osf; Scuffed; Over 25mm

4 Shelfload Cover Rear; Missing; Replace

Click to enlarge image

