



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

AP65KZM - NISSAN QASHQAI TEKNA **NAMA** 4

VIN:	SJNFEAJ11U1594400		**Engine No:**	240305A	
Transmission:	Automatic	**Odometer:**	44855	**Reg Date:**	11/01/2016
Fuel Type:	Petrol	**Engine CC:**	1197	**Colour:**	SILVER
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	Panoramic roof	Heated windscreen
Heated seats	Leather or substitute	AUX/USB	Radio/CD
Cruise control	Climate control	Air con	


Tyre Tread Depths

OSF	2.0	**OSR**	5.0	**NSF**	1.6	**NSR**	5.0
Spare		**Type**	None			**Run Flats**	0

Damage Details

1	**Wheel nsr**	Scratched Over 50mm	Smart Repair
2	**Wheel osr**	Scratched Over 50mm	Smart Repair
3	**Wing osf**	Dented 2 Or Less UpTo 10mm	Smart Repair
4	**Rear TowEye Cvr**	Broken Replace	Replace
5	**Glove Box Lid**	Scuffed Over 25mm	Smart Repair
6	**Door nsf**	Dented With Paint Damage	Repair and Refinish
7	**Bumper Front Moulding**	Scuffed (Unpainted) Over 100mm	Smart Repair
8	**Roof Lining**	Scuffed Over 25mm	Smart Repair
9	**Wheel nsf**	Scratched Over 50mm	Smart Repair
10	**Wheel osf**	Scratched Over 50mm	Smart Repair
11	**Bonnet**	Dented Over 30mm	Repair and Refinish
12	**Door osf**	Dented Between 10mm + 30mm	Smart Repair
13	**Bumper Rear**	Scratched 25 to 100mm Thru Paint	Smart Repair
14	**Door Pad osr**	Scuffed Over 25mm	Smart Repair
15	**Tailgate**	Dented Between 10mm + 30mm	Smart Repair
16	**B Post os**	Scratched Over 25mm Thru Paint	Refinish

Sectional Damage Summary



17	Qtr Panel osr	Scratched Over 25mm Not Thru Paint	Machine Polish
	Qtr Panel nsr	Dented 2 Or Less UpTo 10mm	Smart Repair
18	B Post ns	Dented Over 2 UpTo 10mm	Smart Repair
19	Door osr	Scratched Over 25mm Thru Paint	Refinish
20	Door osr	Dented Between 10mm + 30mm	Report Only
21	Bumper Front	Scratched Over 100mm Thru Paint	Refinish
22	Door nsr	Scratched UpTo 25mm Thru Paint	Smart Repair
	Door nsr	Scratched Over 25mm Not Thru Paint	Report Only

Damage Images

1

Wheel nsr

2

Wheel osr

3

Wing osf

4

Rear TowEye Cvr

5

Glove Box Lid

6

Door nsf

7

Bumper Front Moulding

8

Roof Lining

9  Wheel nsf	10  Wheel osf	11  Bonnet	12  Door osf
13  Bumper Rear	14  Door Pad osr	15  Tailgate	16  B Post os
17  Qtr Panel osr	18  B Post ns	19  Door osr	20  Door osr
21  Bumper Front	21  Bumper Front	22  Door nsr	

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Additional	 Front Interior	 Rear Interior
 Load Area			

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford

Inspector's Name:	RM	Date:	13/10/2025