



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

C19BBD - MERCEDES-BENZ E 220 D **NAMA** 2

VIN:	WDD2383142F099434		**Engine No:**	65492080383670	
Transmission:	Automatic	**Odometer:**	59161	**Reg Date:**	15/03/2019
Fuel Type:	Diesel	**Engine CC:**	1950	**Colour:**	GREY
Body:	Coupe	**Seats:**	4	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Heated seats	Leather or substitute
AUX/USB	Radio/CD	Cruise control	Climate control
Air con	Sat nav		


Tyre Tread Depths

OSF	4.0	**OSR**	5.0	**NSF**	4.0	**NSR**	4.0
Spare		**Type**	None			**Run Flats**	0


Damage Details

1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
2	**Wheel osf**	Scratched Up To 50mm	Smart Repair
3	**Bonnet**	Scratched UpTo 25mm Thru Paint	Smart Repair
4	**Wheel nsr**	Scratched Over 50mm	Smart Repair
5	**Door osf**	Chipped 1 To 5	Smart Repair
6	**Bumper Rear**	Poor Previous Repair Paint Flake	Refinish
7	**Seat Base Cover osf**	Scuffed UpTo 25mm	Smart Repair
8	**Sill os**	Scratched Over 25mm Not Thru Paint	Machine Polish
9	**C Post ns**	Dented Between 10mm + 30mm	Smart Repair
10	**Bumper Front**	Scratched 25 to 100mm Thru Paint	Smart Repair

Sectional Damage Summary



Damage Images

1

Wheel nsf

2

Wheel osf

3

Bonnet

4

Wheel nsr

5

Door osf

6

Bumper Rear

7

Seat Base Cover osf

8

Sill os

9

C Post ns

10

Bumper Front


Beauty Images


OSF


NSF


OSR


NSR


Interior


Rear Interior


Load Area

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	KW	**Date:**	17/10/2025