



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

CA71GMG - HYUNDAI IONIQ PREMIUM

NAMA 3

VIN:	KMHC851JUNU083853		**Engine No:**	EM10M6H0224J	
Transmission:	Automatic	**Odometer:**	71070	**Reg Date:**	02/11/2021
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	GREY
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Heated seats	AUX/USB
Radio/CD	Cruise control	Climate control	Air con
Sat nav			


Tyre Tread Depths

OSF	7.0	**OSR**	4.0	**NSF**	4.0	**NSR**	5.0
Spare		**Type**	Inflation Kit			**Run Flats**	0


Damage Details

1	**Wheel nsr**	Scratched Over 50mm	Smart Repair
2	**Wheel osr**	Scratched Over 50mm	Smart Repair
3	**A Post ns**	Scratched UpTo 25mm Thru Paint	Smart Repair
4	**Door nsf**	Dented Over 30mm	Repair and Refinish
5	**Wheel nsf**	Scratched Over 50mm	Smart Repair
6	**Wheel osf**	Scratched Over 50mm	Smart Repair
7	**Door Pad nsr**	Scuffed Over 25mm	Smart Repair
8	**Bumper Rear**	Poor Previous Repair Poor Paint	Refinish
9	**Door Pad osr**	Scuffed UpTo 25mm	Smart Repair
10	**Lamp osr**	Broken Replace	Replace
11	**Door Pad nsf**	Scuffed UpTo 25mm	Smart Repair
12	**Door osr**	Scratched UpTo 25mm Thru Paint	Smart Repair
13	**Door osr**	Dented 2 Or Less UpTo 10mm	Report Only
14	**Sill ns**	Scratched UpTo 25mm Thru Paint	Smart Repair
15	**Door nsr**	Dented Between 10mm + 30mm	Smart Repair

Sectional Damage Summary



Damage Images

1

Wheel nsr

2

Wheel osr

3

A Post ns

4

Door nsf

5

Wheel nsf

6

Wheel osf

7

Door Pad nsr

8

Bumper Rear

9

Door Pad osr

10

Lamp osr

11


Door Pad nsf

12

Door osr

13

Door osr

14

Sill ns

15

Door nsr


Beauty Images



OSF



NSF



OSR


NSR


Additional


Interior


Rear Interior


Dashboard


Load Area

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	TW	**Date:**	23/10/2025