



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

CK71ZTU - HYUNDAI IONIQ PREMIUM

NAMA 3

VIN:	KMHC851JUNU083850		**Engine No:**	EM10M770094J	
Transmission:	Automatic	**Odometer:**	87570	**Reg Date:**	02/11/2021
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	RED
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Climate control	Air con	Sat nav


Tyre Tread Depths

OSF	4.0	**OSR**	3.0	**NSF**	4.0	**NSR**	4.0
Spare		**Type**	None			**Run Flats**	0

Damage Details


1	**Carpets Front**	Holed Over 3mm	Replace
2	**General Interior**	Soiled Light	Clean
	Wing osf	Previous Repair	Report Only
	Wing nsf	Previous Repair	Report Only
3	**Wheel nsf**	Scratched Over 50mm	Smart Repair
4	**Moulding osf Wing**	Missing Replace	Replace
5	**Roof**	Dented Between 10mm + 30mm	Smart Repair
6	**C Post os**	Chipped 1 To 5	Smart Repair
7	**Door osf**	Dented Between 10mm + 30mm	Smart Repair
8	**Bumper Rear**	Scratched 25 to 100mm Thru Paint	Smart Repair
	Bumper Rear	Previous Repair	Report Only
9	**B Post os**	Scratched UpTo 25mm Thru Paint	Smart Repair
10	**Qtr Panel osr**	Dented Between 10mm + 30mm	Smart Repair
11	**Qtr Panel nsr**	Dented Between 10mm + 30mm	Smart Repair
12	**Qtr Panel nsr**	Scratched UpTo 25mm Thru Paint	Report Only
13	**B Post ns**	Scratched UpTo 25mm Thru Paint	Smart Repair


Sectional Damage Summary



14	**Door osr**	Dented Between 10mm + 30mm	Smart Repair
15	**C Post ns**	Scratched UpTo 25mm Thru Paint	Smart Repair
16	**Bumper Front**	Dented With Paint Damage	Repair and Refinish
17	**Door nsr**	Dented Between 10mm + 30mm	Smart Repair

Damage Images

1

Carpets Front

2

General Interior

3

Wheel nsf

4

Moulding osf Wing

5

Roof

6

C Post os

7

Door osf

8

Bumper Rear

8

Bumper Rear

9



B Post os

10



Qtr Panel osr

11

Qtr Panel nsr

12  Qtr Panel nsr	13  B Post ns	14  Door osr	15  C Post ns
16  Bumper Front	16  Bumper Front	17  Door nsr	

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Additional	 Additional	 Interior
 Load Area	 OSR Interior		

Inspection Notes : D			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	20/10/2025