



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

CK72FKF - FORD KUGA ST-LINE X **NAMA** 3

VIN:	WF0FXXWPMFNM86638		**Engine No:**	NM86638	
Transmission:	Manual	**Odometer:**	14233	**Reg Date:**	02/09/2022
Fuel Type:	Petrol	**Engine CC:**	1496	**Colour:**	RED
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	Sunroof	Heated seats
Air con			


Tyre Tread Depths

OSF	4.0	**OSR**	4.0	**NSF**	4.0	**NSR**	4.0
Spare		**Type**				**Run Flats**	0








Damage Details

1	**Fascia Panel**	Scuffed Over 25mm	Smart Repair
2	**Carpets Front**	Soiled Light	Clean
3	**Seat Base Cover nsr**	Soiled Light	Clean
4	**Door osf**	Chipped Edge Chip	Smart Repair
5	**Seat Base Cover osf**	Torn Over 3mm	Replace
6	**Qtr Panel osr**	Scratched Over 25mm Not Thru Paint	Machine Polish
7	**A Post os**	Dented Between 10mm + 30mm	Smart Repair
8	**A Post os**	Scratched Over 25mm Not Thru Paint	Report Only
9	**Glove Box Lid**	Broken Replace	Replace
10	**Sill ns**	Dented Between 10mm + 30mm	Smart Repair
11	**Door nsf**	Dented Over 30mm	Repair and Refinish
12	**Bumper Front**	Scratched Over 25mm Not Thru Paint	Machine Polish
13	**Door nsr**	Chipped Edge Chip	Smart Repair



Sectional Damage Summary



Damage Images

1  Fascia Panel	2  Carpets Front	3  Seat Base Cover nsr	4  Door osf
5  Seat Base Cover osf	6  Qtr Panel osr	7  A Post os	8  A Post os
9  Glove Box Lid	10  Sill ns	11  Door nsf	11  Door nsf
12  Bumper Front	13  Door nsr		

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Interior	 OSR Interior	 Dashboard
 Additional	 Boot		

Inspection Notes :			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RB	**Date:**	20/10/2025