



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

CN66POH - CITROEN C4 CACTUS FLAIR

NAMA 4

VIN:	VF70PHMZBGE556278		**Engine No:**	B2150399994	
Transmission:	Semi-Automatic	**Odometer:**	37305	**Reg Date:**	21/09/2016
Fuel Type:	Petrol	**Engine CC:**	1200	**Colour:**	GREY
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Air con	Sat nav	


Tyre Tread Depths

OSF	5.0	**OSR**	5.0	**NSF**	5.0	**NSR**	6.0
Spare		**Type**	Space Saver			**Run Flats**	0


Damage Details


1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
2	**Fascia Trim**	Missing Replace	Replace
3	**Wheel osf**	Scratched Over 50mm	Smart Repair
	Door osf	Dented Between 10mm + 30mm	Smart Repair
4	**Qtr Panel Moulding ns**	Scuffed (Unpainted) UpTo 100mm	Smart Repair
5	**Qtr Panel Moulding os**	Scuffed (Unpainted) Over 100mm	Smart Repair
	Qtr Panel osr	Previous Repair	Report Only
6	**Door osr**	Poor Previous Repair Poor Paint	Refinish
	Wing nsf	Previous Repair	Report Only
7	**Door nsf**	Dented Over 30mm	Repair and Refinish
8	**Bumper Front**	Poor Previous Repair Poor Paint	Refinish
9	**Door nsr**	Dented With Paint Damage	Repair and Refinish

Sectional Damage Summary



Damage Images

1

Wheel nsf

2

Fascia Trim

3

Wheel osf

4

Qtr Panel Moulding ns

5

Qtr Panel Moulding os

6

Door osr

7

Door nsf

8

Bumper Front

9

Door nsr

Beauty Images


OSF



NSF


OSR


NSR



Speedometer


Additional


Interior


Load Area


OSR Interior


Dashboard

Inspection Notes : D			
Conditions:	Wet	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	23/10/2025