



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

DT19SXC - NISSAN JUKE TEKNA CVT **NAMA** 3

VIN:	SJNFBAF15U8065354		**Engine No:**	552743R	
Transmission:	Automatic	**Odometer:**	72304	**Reg Date:**	31/05/2019
Fuel Type:	Petrol	**Engine CC:**	1598	**Colour:**	BLACK
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Heated seats	Leather or substitute	AUX/USB
Radio/CD	Cruise control	Climate control	Air con
Sat nav			


Tyre Tread Depths

OSF	4.0	**OSR**	3.0	**NSF**	5.0	**NSR**	2.0
Spare		**Type**	Inflation Kit			**Run Flats**	0

Damage Details


1	**Shelfload Cover Rear**	Missing Replace	Replace
2	**Wheel nsr**	Corroded Light	Smart Repair
3	**Wheel osr**	Corroded Light	Smart Repair
4	**Door Moulding nsf**	Scuffed (Unpainted) Over 100mm	Smart Repair
5	**Door nsf**	Scratched Over 25mm Thru Paint	Refinish
6	**Wheel nsf**	Corroded Light	Smart Repair
7	**Wheel osf**	Corroded Light	Smart Repair
8	**Moulding nsf Wing**	Scuffed (Unpainted) Over 100mm	Smart Repair
	Roof	Dented 2 Or Less UpTo 10mm	Smart Repair
9	**Bonnet**	Dented Over 2 UpTo 10mm	Smart Repair
10	**Door osf**	Dented 2 Or Less UpTo 10mm	Smart Repair
11	**Door osf**	Scratched Over 25mm Not Thru Paint	Report Only
	B Post os	Scratched UpTo 25mm Thru Paint	Smart Repair
	Qtr Panel osr	Dented 2 Or Less UpTo 10mm	Smart Repair
12	**Qtr Panel osr**	Scratched Over 25mm Not Thru Paint	Report Only
13	**Qtr Panel nsr**	Poor Previous Repair Poor Paint	Refinish

Sectional Damage Summary



14	**Door osr**	Scratched Over 25mm Thru Paint	Refinish
15	**Door osr**	Dented Between 10mm + 30mm	Report Only
16	**Tyre osr**	Punctured Replace	Replace
17	**Bumper Front**	Scratched Over 25mm Not Thru Paint	Machine Polish
18	**Door nsr**	Scratched Over 25mm Thru Paint	Refinish

Damage Images

1

Shelfload Cover Rear

2

Wheel nsr

3

Wheel osr

4

Door Moulding nsf

5

Door nsf

6

Wheel nsf

7


Wheel osf


8

Moulding nsf Wing

9

Bonnet

10

Door osf

11

Door osf

12

Qtr Panel osr

13



Qtr Panel nsr

14




Door osr

15




Door osr

16



Tyre osr

17



Bumper Front

18



Door nsr

Beauty Images



OSF



NSF



OSR



NSR




Dashboard



Additional



Front Interior



Rear Interior



Load Area

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RK	**Date:**	07/10/2025