



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

EA73NZU - FORD PUMA TITANIUM

NAMA 3

VIN:	WF02XXERK2PY57228		**Engine No:**	PY57228	
Transmission:	Manual	**Odometer:**	15645	**Reg Date:**	29/09/2023
Fuel Type:	Hybrid/Electric	**Engine CC:**	999	**Colour:**	BLUE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Heated windscreen	Heated seats
AUX/USB	Radio/CD	Cruise control	Climate control
Air con	Sat nav		


Tyre Tread Depths

OSF	4.0	**OSR**	5.0	**NSF**	3.0	**NSR**	5.0
Spare		**Type**	Inflation Kit			**Run Flats**	0


Damage Details

1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
2	**Bumper Rear**	Poor Previous Repair Poor Paint	Refinish
3	**Door Pad osf**	Burn UpTo 3mm	Smart Repair
4	**Bumper Rear Moulding**	Scuffed (Unpainted) UpTo 100mm	Smart Repair
5	**Bumper Front**	Poor Previous Repair Poor Paint	Refinish

Sectional Damage Summary



Damage Images

1

Wheel nsf

2

Bumper Rear

3

Door Pad osf

4

Bumper Rear Moulding

5

Bumper Front

Beauty Images



OSF



NSF



OSR


NSR


Dashboard


Additional


Front Interior


Rear Interior


Load Area

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RK	**Date:**	10/10/2025