



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

EF70XNU - FORD KUGA ST-LINE ED **NAMA** 2

VIN:	WF0FXXWPMFLS13116		**Engine No:**	LS13116	
Transmission:	Automatic	**Odometer:**	34202	**Reg Date:**	27/01/2021
Fuel Type:	Diesel	**Engine CC:**	1995	**Colour:**	GREY
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Towbar	Alloys	Parking sensors	Heated windscreen
Leather or substitute	AUX/USB	Radio/CD	Cruise control
Climate control	Air con	Sat nav	


Tyre Tread Depths

OSF	4.0	**OSR**	3.0	**NSF**	4.0	**NSR**	3.0
Spare		**Type**	Inflation Kit			**Run Flats**	0

Damage Details

	Wheel nsf	Scratched Up To 50mm	Smart Repair
	Bonnet	Chipped 1 To 5	Smart Repair
	Door osf	Dented Between 10mm + 30mm	Smart Repair
1	**Tailgate Pad**	Scuffed Over 25mm	Smart Repair
	Screen Front	Chipped UpTo 10mm	Smart Repair
2	**Bumper Rear Moulding**	Scratched (Painted) UpTo 25mm Thru Paint	Smart Repair
3	**Bumper Rear Moulding**	Scratched (Painted) Over 25mm Thru Paint	Report Only
	Door nsf	Dented 2 Or Less UpTo 10mm	Smart Repair
	Door nsr	Dented 2 Or Less UpTo 10mm	Smart Repair


Sectional Damage Summary



Damage Images

1  Tailgate Pad	2  Bumper Rear Moulding	3  Bumper Rear Moulding

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Additional	 Interior	 Load Area
 OSR Interior			

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	10/10/2025