



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

EJ23HVA - KIA SPORTAGE 2 ISG **NAMA** 1

VIN:	U5YPU81BLPL154061		**Engine No:**	G4FPPZ563468	
Transmission:	Manual	**Odometer:**	20250	**Reg Date:**	28/04/2023
Fuel Type:	Petrol	**Engine CC:**	1598	**Colour:**	GREY
Body:	Estate	**Seats:**	5	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Climate control	Air con	


Tyre Tread Depths

OSF	3.0	**OSR**	5.0	**NSF**	3.0	**NSR**	5.0
Spare		**Type**	Inflation Kit			**Run Flats**	0


Damage Details

1	**Seat Base Cover osr**	Soiled Light	Clean
2	**Door Pad osr**	Soiled Light	Clean
3	**Qtr Panel nsr**	Scratched Over 25mm Not Thru Paint	Machine Polish
4	**Door nsf**	Chipped 1 To 5	Smart Repair



Sectional Damage Summary



Damage Images

1  Seat Base Cover osr	2  Door Pad osr	3  Qtr Panel nsr	4  Door nsf

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Interior	 Load Area	 OSR Interior

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	17/10/2025