



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

FL20CVA - MINI COOPER S ELECTRIC **NAMA** 2

VIN:	WMWXP320502N00357		**Engine No:**	F081A212	
Transmission:	Automatic	**Odometer:**	35412	**Reg Date:**	15/06/2020
Fuel Type:	Hybrid/Electric	**Engine CC:**		**Colour:**	BLUE/BLACK
Body:	Hatchback	**Seats:**	4	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	Sunroof	Heated seats
Air con			


Tyre Tread Depths

OSF	4.0	**OSR**	4.0	**NSF**	4.0	**NSR**	4.0
Spare		**Type**				**Run Flats**	0








Damage Details

1	**Wheel nsf**	Scratched Over 50mm	Smart Repair
2	**Wheel osf**	Scratched Over 50mm	Smart Repair
3	**Seat Base Cover osr**	Soiled Light	Clean
4	**Bonnet**	Dented With Paint Damage	Repair and Refinish
5	**Wheel nsr**	Scratched Over 50mm	Smart Repair
6	**Door osf**	Chipped Edge Chip	Smart Repair
7	**Door osf**	Dented Between 10mm + 30mm	Report Only
8	**Wheel osr**	Corroded Light	Smart Repair
9	**Tailgate**	Scratched Over 25mm Not Thru Paint	Machine Polish
10	**Qtr Panel osr**	Scratched Over 25mm Not Thru Paint	Machine Polish
	Qtr Panel nsr	Previous Repair	Report Only
11	**Bumper Front**	Scratched 25 to 100mm Thru Paint	Smart Repair
12	**Door Mirror Assy nsf**	Scratched (Painted) UpTo 25mm Thru Paint	Smart Repair



Sectional Damage Summary



Damage Images

1  Wheel nsf	2  Wheel osf	3  Seat Base Cover osr	4  Bonnet
4  Bonnet	5  Wheel nsr	6  Door osf	7  Door osf
8  Wheel osr	9  Tailgate	10  Qtr Panel osr	11  Bumper Front
11  Bumper Front	12  Door Mirror Assy nsf		

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Additional	 Interior	 Dashboard
 OSR Interior	 Boot	 Additional	 Additional

Inspection Notes : 2x charging leads			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	TW	**Date:**	24/10/2025